GMTech2 Module and VCI Self-Testing

1. Inset the software card you need


2. Connect the self-testing plug into the tech2 module.

3. Enter the Main Menu and choose f4 'tool options'

Main Menu

F0: Diagnostics
F1: Service Programming System
F2: View Captured Data
F3: GM Performance Parts Diagnostics
F4: Tool Options
F5: Getting Started

4. Choose F3   'Self Test '

Tool Options

F0: Set Clock
F1: Set Screen Contrast
F2: Set Units
F3: Self Test
F4: Programming TECH 2
F5: Set Communication By-Pass
F6: Set Language
F7: CANdi Diagnostics

5. Press Exit

Before running the Tech 2 sel

   1. CANdi must not be conr
   2. ALDL loopback should b
      connected (GM3000109).
   3. Failure to follow thes
      instructions may invalid
      the self test.

   Press [EXIT] to continue

6 Select the Self-Testing Options

Tech 2 Self Test
Version 6.40

0: Automated Main PCB and V
1: Automated Main PCB
2: Automated VCI
3: Selectable Main PCB
4: Selectable VCI
5: Power On Self Test Resul
6: Hardware ID

7. VCI Self-Testing

8. VCI Test Result